

2" JIS Bullet™ ASSEMBLY (T.G.)Parts List

ITEM	PART NO.	QTY.	DESCRIPTION
	B2-6001	1	ASSEMBLY
1	B2-3301	4	SPLITTER BODY SPACER (MODULAR)
2	B2-5101	1	JIS NOSE CONE
3	B2-5801	4	JIS GUIDE ROLLER (T.G.)
4	B2-6101	1	50MM EXPANDER (T.G.)
5	B2-7301	1	2" JIS SPLITTER BODY SET (T.G.)
6	B2-901	1	1.312 DIA. CUTTER WHEEL
7	B2-902	1	1.937 DIA. CUTTER WHEEL
8	B2-903	1	2.187 DIA. CUTTER WHEEL
9	B2-904	1	2.875 DIA. CUTTER WHEEL
10	B2-8001	12	SPLITTER BODY SCREW
11	MCI00019	2	1/2" DIA X 1-3/4"LG DOWEL PIN
12	MCI00023	5	5/16" DIA X 1"LG DOWEL PIN
13	MCI00024	3	3/8" DIA X 1"LG DOWEL PIN

NOTES:

2. STAMP SERIAL NUMBER ON FLAT AS SHOWN.
MMI JOB NO. XXXXXXX-XX 01, 02, ECT.
(TYP. N.S. & F.S.)
3. STAMP MMI LOGO & U.S. PAT. NUMBER ON FLAT AS SHOWN. (TYP. N.S. & F.S.)
4. 75mm EXPANDER SHOWN FOR INSTALLATION INFORMATION.

DRAWING REVISION HISTORY LISTING

PART NO: B2-6001

DESCRIPTION: 2" JIS Bullet™ ASSEMBLY (T.G.)

<u>APPR.</u>	<u>REV</u>	<u>DATE</u>	<u>BY</u>	<u>DESCRIPTION OF REVISION</u>
doug	D	03/19/96	TLW	CHANGED TO NEW BOLT TOGETHER SPLITTER BODY DESIGN FOR (O.G.) DESIGN WAS WELDED SLOT.
doug	E	04/15/96	TLW	CHANGED SERIAL NUMBER TO JOB NUMBER XXXXXXXX-XX 01, 02, ECT.
doug	F	09/12/96	TLW	ADDED ITEM #'S TO DRAWING TO MATCH PARTS LIST. ADDED 1/8 FILLET WELD 3/4" FORM END 1/2" LONG TYP. (4) PLCS. BOTH ENDS. THIS IS TO PREVENT THE SIDE PLATE FROM PEELING OFF WHILE SPLITTING PIPE. PER. DOUG DUNCAN.
SWB	-	04/21/98	TLW	CORRECTED ITEM #10 (MAC00055) 1/4-20NC X 1" LG SHCS STL PL TO (B2-8001) SPLITTER BODY SCREW.