



McElroy Manufacturing, Inc.

The leader by design.


Tulsa, Oklahoma U.S.A.

DRAWN: MLM	CHECK: BA	APPRV'D: RAD	DATE: 5/14/99	DWG No: T9013800	SHT No: 1	REV No: A	PART No: T9013801
------------	-----------	--------------	---------------	------------------	-----------	-----------	-------------------

TracStar 900 GENERATOR FUSE BOX ASSEMBLY

CAD No: T9013801

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.



UNLESS NOTED OTHERWISE:	(3) PLC. DIM'S .XXX = $\pm 0.005''$ (2) PLC. DIM'S .XX = $\pm 0.010''$ FRACTIONAL DIM'S = $\pm 1/32''$	ANGULAR DIM'S = $\pm 1/4''$ REMOVE ALL BURRS BREAK ALL SHARP EDGES	STAMP OR ETCH P/N ON ALL DETAIL PARTS
-------------------------	--	--	---------------------------------------

MMI NUMBER	ITEM	QTY.	ASSEMBLY	SIZE AND DESCRIPTION

**TracStar 900 GENERATOR FUSE BOX ASSEMBLY**Parts List

ITEM	PART NO.	QTY.	DESCRIPTION
	<b>T9013801</b>		<b>ASSEMBLY</b>
F63,F64,F65 3 SPARES	MLQ00031	6	60 AMP FUSE, FRN-R-60
1	T9013802	1	GENERATOR FUSE BOX MODIFICATION
2	T9013803	1	PANEL MODIFICATION
3	MLR00008	1	FUSE BLOCK
4	MLR00011	3	FUSE COVER(NOT SHOWN)
5	MAC00276	2	#10-32NF X 1/2LG SHCS
6	MLM00093	2	GROUND LUG
7	MAE00083	2	#10-32NF X 1/2LG BHSCS
8	MBA00024	2	#10-32NF HEX NUT STL PL
9	829201	1	DANGER HIGH VOLTAGE LABEL
10	T9016701	1	HEATER FUSE LABEL

**NOTES:**

1. PUT SPARES IN PLASTIC BAG AND PLACE IN RADIO TRAY.

## DRAWING REVISION HISTORY LISTING

**PART NO:** T9013801  
**DESCRIPTION:** GENERATOR FUSE BOX ASSEMBLY

<u>APPR.</u>	<u>REV</u>	<u>DATE</u>	<u>BY</u>	<u>DESCRIPTION OF REVISION</u>
BA	A	9/1/99	MLM	ADDED ITEM 9-(829201 LABEL) AND ITEM 10-(T9016701 LABEL)
RAD	----	9/24/99	MLM	ADDED 3 SPARE FUSES (MLQ00031) AND NOTE.