



McElroy Manufacturing, Inc.
The leader by design.
Tulsa, Oklahoma U.S.A.


DRAWN: DJL	CHECK: SW	APPRV'D: B	DATE: 8/24/97	SHT No: 2	REV No: D	PART No: 1814002
------------	-----------	------------	---------------	-----------	-----------	------------------

CARRIAGE MANIFOLD ASSEMBLY

NOTE: THIS DRAWING AND THE INFORMATION CONTAINED THEREIN IS THE CONFIDENTIAL AND PROPRIETARY PROPERTY OF McElroy Manufacturing, Inc. THE DRAWING IS NOT TO BE REPRODUCED IN ANY MANNER, SUBMITTED OUTSIDE PARTIES FOR EXAMINATION, OR USED DIRECTLY OR INDIRECTLY FOR THE PURPOSES OTHER THAN THOSE FOR WHICH IT WAS FURNISHED WITHOUT WRITTEN PERMISSION OF McElroy Manufacturing, Inc.

NOTES:

1. FOR REPLACEMENT LABEL ORDER PART NUMBER 816301.



CARRIAGE MANIFOLD ASSEMBLYPARTS LIST

ITEM	PART NO.	QTY	DESCRIPTION
	1814002		Assembly
1	1814003	1	CARRIAGE MANIFOLD WITH PLUGS
2	816301	1	FACING, HEATING, FUSING, PRESSURE SELECTOR LABEL

DRAWING REVISION HISTORY LISTING

PART NO: 1814002
DESCRIPTION: CARRIAGE MANIFOLD ASSEMBLY

<u>APPR.</u>	<u>REV</u>	<u>DATE</u>	<u>BY</u>	<u>DESCRIPTION OF REVISION</u>
TLW	A	12/18/97	TGW	REVISED ASSY TO BE Datalogger READY. ADDED ITEMS 5, 6, 7 & 8. REVISED ITEM 3 QTY FROM (4) TO (3).
SWB	B	2/25/98	TGW	CORRECTED DRAWING BY ADDING NOTE 4 TO INSTALL PLUGS IN PORTS "T" & "P" FOR #28 UNITS.
TLW	C	6/16/98	TGW	REMOVED Datalogger FITTINGS (ITEM 5 MFC00078, ITEM 6 MFB00167, ITEM 7 MFH00034 & ITEM 8 MFH00032) - NOW IN "TRANSDUCER CONNECTION KIT" P/N ADL1401. REMOVED ITEM 3 PLUGS (MFC00004) - NOW CALLED OUT ON PLUMBING SCHEMATICS. CHANGED ITEM 4 LABEL TO ITEM 3. REMOVED NOTES 2, 3 & 4.
SWB	D	10/28/05	BWW	REVISED TO REMOVE MFL00013 AND 1814001 WHICH ARE NOW CALLED OUT ON NEW ITEM 1 1814003 TO ENSURE REPLACEMENT MANIFOLD CONTAINS EXPANSION PLUGS. REMOVED 1814003 AND 816301 FROM FACE OF DRAWING TO PREVENT PURCHASE OF MANIFOLD WITHOUT LABEL. CHANGED NOTE 1 FOR ORDERING REPLACEMENT LABEL.